Exterior Bdys. T 5 N., R.28 E., W.M. As surveyed by Timothy W. Davenport, U.S.Dept.Surveyor, Under Contract No. 101,
Dated Aug. 5, 1861.

,	Chains	Monday, Sept.9, 1861.
		Beginning at the post, the established Cor. to Tps. 5 N.,
		Rs. 28 & 29 E., on the 1st Standard Parallel N.
		Thence
		N. bet. Secs. 31 & 36.
		Var.21°E.
	40.00	Set & Sec. Cor.; made mound and drove charred stake, as
		per instructions.
	80.00	Set post Cor. to Secs. 30, 31, 25 & 36; made mound and demos
		posited charred stake as per instructions.
		Surface; undulating.
		Soil; sandy, with heavy sage and greasewood. In vacant
		places, bunch grass.
	3.	pares, value graps.
		N. bet. Secs. 25 & 30.
		The state of the s
	40.00	Var.20°30'E.
	40.00	Set post for & Sec. Cor.
	2012074000000	Made mound and drove charred stake, as per instructions.
	80.00	Set post Cor. to Secs. 19, 30, 24 & 25; made mound and
		deposited charred stake as per instructions.
		N. bet. Secs. 19 & 24.
		Var.20°30'E.
	40.00	Set & Sec. post; made mound and drove charred stake, as per
		instructions.
	58.00	Main Columbia Trail , course E. & W.
	80.00	Set post Cor. to Secs. 13, 18, 19 & 24; made mound and de-
		posited charred stake, as per instructions.
		This mile has less sage and greasewood than the previous
		ones.
	383.3	Surface; some rocky.
		Juliane, some rocky.
		N bot See 17 4 10
	W.	N. bet. Secs. 13 & 18.
	#2 100000 0000	Var.20°30'E.
	40.00	Set & Sec. post; made mound and deposited charred stake, as
		per instructions.