Subdivisional Lines, T 5 N R 31 E W M.

	Chains.	
	80.00	Drove charred stake & raised mound of earth, with pits, etc.,
	00.00	as per instructions, for Cor. to Secs. 21, 22, 27 & 28.
		Drove pine stake, 2 ft. long, 2 ins. sq., in S.E. pit.
		Land; rolling.
		Soil; 1st rate. Good grass.
		5011, 250 1400 500 8200
	= 1	
		E. on random line bet. Secs. 22 & 27.
	40.00	Set temp. ½ Sec. Cor.
	80.30	Intersect N. & S. line at Cor.
		W. on true line.
	40.15	Drove charred stake & raised mound of earth, with pits, etc.,
		as per instructions, for & Sec. Cor.
	80.30	The Cor.
		Land; rolling.
		Soil; 1st rate.
		2
		* :
		N. bet. Secs. 21 & 22.
		Var.21°30'E.
	40.00	Drove charred stake & raised mound, with pits, etc., as per
4		instructions, for & Sec. Cor.
	80.00	Drove charred stake & raised mound, with pits, etc., as
		per instructions, for Cor. to Secs. 15, 16, 21 & 22.
		Drove pine stake, 2 ft. long, 2 ins. sq., in S.E. pit.
		Land; rolling.
		Soil; lst rate.
		E. on random line bet. Secs. 15 & 22.
	40.00	Set temp. 4 Sec. Cor.
	80.00	Intersect N. & S. line at Cor.
	00.00	W. on true line.
	40.00	Drove charred stake; raised mound, with pits, etc., as per
	40.00	instructions, for \(\frac{1}{4}\) Sec. Cor.
	80.00	20 215 200
	80.00	The Cor.
		Land; rolling. Soil; 1st rate. Good grass.