## Subdivisional Lines, T 5 N R 32 E W M.

Chains	S.89°33' W. on true line.
40.35	Drove charred stake and raised mound of earth, with pits,
34334533	etc., as per instructions, for \$ Sec. Cor.
80.70	The Cor.
	Land; gently rolling.
_ 7	Soil; 1st rate. Good grass.
	N. bet. Secs. 26 & 27.
	Var.20°45'E.
30.00	Enter flat, brs. N.W. & S.E.
40.00	The state of the s
40.00	Drove charred stake and raised mound of earth, with pits,
	etc., as per instructions, for \( \frac{1}{4} \) Sec. Cor.
61.00	Leave flat, brs. N.W. & S.E.
80.00	Drove charred stake and raised mound of earth, with pits,
	etc., as per instructions, for Cor. to Secs. 22, 23, 2 and 27.
	Drove willow stake, 2 ft. long, 2 ins. sq., in S.E. pit.
	Land; flat level, upland, gently rolling.
	Soil; 1st rate.
8 *	E. on random line bet. Secs. 23 & 26
40.00	Setttemp. & Sec. Cor.
80.75	Intersect N. & S. line, 60 lks. S. of Cor.
	S.89° 34' W. on true line.
40.38	Drove charred stake and raised mound of earth, with pits,
	etc., as per instructions, for & Sec. Cor.
80.75	The Cor.
	Land; rolling.
	Soil; 1st rate. Good grass.
	Jorr, 150 rave. Good grass.
	N. bet. Secs. 22 & 23.
0	Var.21°E.
40.00	Drove charred stake and raised mound of earth, with pits,
	etc., as per instructions, for 4 Sec. Cor.