Exterior Lines, T 5 N R 34 E W M.

	Chains	to be 1.47 S. of post.
8		True line will be S.89°50'E.
W ×		True line will be 5.55 50 2.
		S.89°50'E. on true line on N. Bdy. of Sec.6, T 5 N. Var.21°E.
	38.44	Set ½ Sec. post on E. side of ravine, 40 ft. deep. Drove
		charred stake; dug pits & raised mound, as per instruct ions.
	78.44	Set post Cor. for Secs. 5, 6, 31 & 32. Drove charred stake
		dug pits and raised mound, as per instructions.
		Land; very broken.
		Soil; hardly 2nd rate.
		boll, hardly and lave.
	2.0	
		S.89°50'E. on true linerbet. Secs. 5 & 32.
		Var.21°E.
	40.00	Set & Sec. post; drove charred stake; dug pits and raised
		mound, as per instructions.
	80.00	
		dug pits and raised mound, as per instructions.
		Land; broken. Grass good.
		Soil; 2nd rate.
		April 14th, 1865:
		S.89°50'E. on true line ontw. Bdy. of Secs. 4.
		Var.21°E.
	40.00	Set 1/2 Sec. post; drove charred stake; dug pits and raised
		mound, as per instructions.
	80.00	Set post Cor. for Secs. 3, 4, 33 & 34. Drove charred stake
	3 = -	dug pits and raised mound, as per instructions.
		This line passes over hilly land. Good grass.
		Soil; 2nd rate.
		W F I was 1 W
	ga a .	
	25	S.89°50' E. on N. Bdy. of Sec. 3.
	3.50	Var.21° E.