## Subdivisional Lines, T 5 N R 35 E W M.

Chains	
40.00	Set & Sec. post; drove charred stake; dug pits & raised
	mound, as per instructions.
80.00	Set post Cor. for Secs. 5, 6, 7 & 8; drove charred stake;
	dug pits & raised mound, as per instructions.
	Land; broken.
	Grass; 2nd rate.
	Soil; poor 2nd rate.
	E. on random bet. Secs. 5 & 8.
40.00	
79.85	
	4, 5, 8 & 9; from which, I run
Iv =	S.89°34' W. on true line.
39.92	
2 -1 -0	mound, as per instructions.
79.85	To post Cor. for Secs. 6, 7, 5 & 8.
	Land; broken.
	Grass good.
	Soil; 2nd rate.
	Н
	W. on random bet. Secs. 6 & 7.
40.00	The state of the s
80.17	
	run
1	N.89°39' E. on true line.
40.17	2 31
1011	mound, as per instructions.
80.17	CALL PRODUCTION CONTRACTOR CONTRA
00.17	Land; broken.
	Grass poor.
	Soil; gravel.
	DOLL, STAVEL
1 - 5	April 16th, 1865.
7	N. on random bet. Secs. 5 & 6.
	var.21° E.