CORNER RESTORATION FORM

Township 4N Range 29E Section 29, 30 County UMATILLA

State OREGON Date 3/30/2023 Number T-5

Corner Designation : 1/4 CORNER: 29, 30

X Condition Report Only
___ Not Found
X Renewed
___ Surveyed In
___ Referenced

Previous Renewals ORIGINAL SOURCE OF CORNER

ORIGINALLY SURVEYED IN 1861 BY DAVENPORT UNDER
CONTRACT #101, HE SET A STAKE IN MOUND OF EARTH
1980 KRUMBEIN SET A BRASS CAP IN PLACE OF WAGON AXLE
COUNTY SURVEY NO. S-158-C

MONUMENT DETAIL

X Found X Set



BASIS OF BEARINGS, NAD 83/91 OREGON STATE PLANE COORDINATES NORTH ZONE:

NORTHING: 779816.16
EASTING: 8527093.09

Monument & Accessories Set/Found (Procedure and Description)

FOUND A 2-3/8" BRASS CAP 4" BELOW GRADE IN ROAD, STAMPING NOT LEGIBLE, RESTAMPED AS SHOWN, COUNTY SURVEY NO. S-158-C

FOUND A METAL TELEPHONE WARNING SIGN POST S 61°14' E 32.56', CORNER FORM NO. T5-95-060-B

FOUND A 1"X30" IRON PIPE W/ 2-3/8" BRASS CAP W.C. & UMATILLA MON. SIGN N 44°56' W 18.68', CORNER FORM NO. T5-95-060-B

FOUND A 1"X30" IRON PIPE W/ 2-3/8" BRASS CAP W.C. & UMATILLA MON. SIGN S 46°03' W 16.32', CORNER FORM NO. T5-95-060-B

FOUND A ALUMINUM TAG 951 ON RAILROAD TIE POST N 46°31' E 41.08', CORNER FORM NO. T5-95-060-B

Sketch of Monument, Accessories and General Area



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
MAY 10, 2011
LANCE CLARK KING
61420

RENEWS: 6/30/2023

Agency:
CK3, LLC
945 W. ORCHARD
HERMISTON OREGON 97838
OFFICE: 541-567-2345
FAX: 541-567-2305
WEB: CK3LLC.NET
Field Book # 0-350

COUNTY SURVEYOR RECORDING INFO

Received CT
Filed 5/4/23
Survey No. 23-042-C
Drawing No.
Index No. T-5