OREGON CORNER RESTORATION FORM

Section 24, 25 Township 5N Range 30E
County Umatilla Date: 05-08-2006

Corner Designation: 5N30E R23

_____	Condition Report Only
____X____	Not Found
_____	Remonumented
_____	Unrecorded
____X____	Surveyed In
____X____	Referenced Out

Previous Renewals / Surveys, etc.

12-1861 S.Payne - Subdv (100) "Set charred stake with mound trench and pits as per instrct's for 1/4 sec corner."
06-1974 D.Krumbein (I-24-B) East-West line shown only (no location).
06-1974 D.Krumbein (I-167-B) East-West line shown only (no location).
12-1974 D.Krumbein (I-168-B) East-West line shown only (no location).
06-1979 L.Jones (Q-1129-C) East-West line shown only (no location).

Monument and Accessories Found: (condition and source)
Searched for charred stake, not found. Plowed field in CRP.

DIAGRAM



5' Steel T-post with a Umatilla County Survey Sign.

● 5/8"dia. x 24" long Iron Rebar with a 1.3"dia. Red plastic cap.

⊕ Set 2-3/8"dia. Brass cap on a 1-1/2" x 30" long Galvanized pipe monument.

Field access road

MONUMENT(S) AND ACCESSORIES SET (Procedures and Description)

Set a 2-3/8"dia.Brass Capped monument (stamped as shown) on a 1-1/4"ID x 30"long galvanized pipe 24" below the ground surface. Set a 5' steel T-Post with a Umatilla County Survey Marker sign facing South 525 feet Southwest of the buried corner. amd West of the NW RM.

REFERENCES SET:

Set four (5/8" dia x 30" long Iron rebar with a 1.3" dia. Red plastic cap) to the bearings and distances from monument shown above in the sketch.

Made GPS tie to TRI Stations
LAURILA RESET RB 1379 and
WALLS RB 1396
Latitude 45 °53'34.27353"N
Longitude 119°00'19.70520"W
NAD 83(1991)

Oregon State Plane Coord. - North Zone
Northing 815152.09
Easting 8582626.74
Ortho Height 1020.48
Ellipsoidal Height 951.27

Location and Comments

Compass Declination
18°E

Surveyors Seal

Proceed Northwest from the junction of HWY 37 and South Cold Springs Highway approximately 0.25 miles. Thence North past the BM#818 at the base of Cold Spring Rances silo along the field access road. North 1.1 miles to the Umatilla County Survey sign East of the road. Thence 550 feet East up the hillside to the buried corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-07

RECEIVED BY:

Date 02-07
Rec'd By: KCH
No.: 07-11-B

Firm / Agency

Haddock Surveying
P. O. Box 1574
Pendleton, OR 97801
(541) 276-2174