OREGON CORNER RESTORATION FORM

Section 26, 35 Township 5N Range 30E
County Umatilla Date: 09-18-2006

Corner Designation: 5N30E V20

_____	Condition Report Only
___X___	Not Found
_____	Remonumented
_____	Unrecorded
___X___	Surveyed In
___X___	Referenced Out

Previous Renewals / Surveys, etc.

12-1861 D.Payne Subdv. (100) "Set charred stake with mound trench and pits as per instrs for 1/4 sec corner.

Monument and Accessories Found: (condition and source)

Searched for and did not find charred stake. Plowed fields.

DIAGRAM



5' Steel T-post with a Umatilla County Survey Sign.

5/8"dia. x 30" long Iron Rebar with a 1.3"dia. Red plastic cap.

Set 2"dia. Aluminum cap on a 5/8" x 30" long Iron Rebar.

5' steel T-post

Wood fence post

RR Tie Wood fence post

MONUMENT(S) AND ACCESSORIES SET (Procedures and Description)

Set a 2"dia.Aluminum Cap (stamped as shown) on a 5/8"dia. x 30"long Iron Rebar 2" above the ground surface on existing fence line.
Set a 5' steel T-Post with a Umatilla County Survey Marker sign facing South 6 inches South of the corner.

REFERENCES SET:

Set two (5/8" dia x 30" long Iron rebar with a 1.3" dia. Red plastic cap) to the bearings and distances from monument shown above in the sketch.

Made GPS tie to TRI Stations
LAURILA RESET RB 1379 and
WALLS RB 1396
Latitude 45 °52'41.87488"N
Longitude 119°01'15.73160"W
NAD 83(1991)

Oregon State Plane Coord. - North Zone
Northing 809758.61
Easting 8578764.01
Ortho Height 1015.68
Ellipsoidal Height 946.40

Location and Comments

Compass Declination
18°E

Surveyors Seal

Beginning 1.5 miles West of HWY 37 and the S. Fork Cold Spring Road. South on Umatilla County Road 1172 (KOSMOS RD) 0.59 miles to a East field access gate. Thence East 0.83 miles to the 1/16th corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-07

RECEIVED BY:

Date 02-07
Rec'd By: LOH/C
No.: 07-206-R

Firm / Agency

Haddock Surveying
P. O. Box 1574
Pendleton, OR 97801
(541) 276-2174