OREGON CORNER RESTORATION FORM

Section: **20, 21, 28, 29**

Township: 6 North

Range: **35 East of the Willamette Meridian**

County: Umatilla

Date: **June 1, 2002**

Corner Indexing Information: **Township 6N Range 35E Corner Code R 9** **(Willamette Meridian)**

Additional Identifier: (e.g. BLM designation for the corner, street intersection, plat name, block, lot, etc.)

This corner is common to sections 20, 21, 28, and 29.

Oregon Plane Coordinates: N: 848691.658 **E:** 8722017.749

Zone: North **Order:** second **Datum:** NAD83-91 **Convergence:** 1°27'01.3" **Scale Factor:** .99995515

Previous Renewals/Surveys, etc.: Originally surveyed by U.S. Deputy Surveyor William Odell under his contract No. 110, dated 8-23-1865. The Surveyor Generals notes state, "set post corner for sections 20,21,28, and 29. Drove charred stake, dug pits, and raised mounds as per instructions." Survey No. 35, dated October 15, 1888, Book 1, Page 188, Arnold set a flat oval shaped boulder 12"x7"x4", 8" below the bottom of a ditch from evidence of the original corner post. Survey I-4, dated 1975, Dwyer found a brass screw. Circa 1995, The Oregon Department of Transportation resurfaced the road and set a brass cap in monument case.

Monument(s) & Accessories Found (Condition & Source):

At the southwest corner of section 21, T6N R35E, found 3" brass cap 5" diameter iron monument case 2 ½" below the surface pavement.

Monument Set (Procedures & Description):



Monument Detail:



New Accessories: WE SET:

A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears N 43°E ~ 32.53 from the corner. No Umatilla County Bearing object sign or t-post set. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears S 47°E ~ 36.35 feet from the corner. No Umatilla County Bearing object sign or t-post set. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears S 43°W ~ 22.83 feet from the corner. Attached a Umatilla County Bearing object to the northeast face of a locust fence post. A 5/8 rebar with yellow plastic cap stamped 'Tomkins Surveying' which bears N 47°W ~ 32.56 feet from the corner. Attached a Umatilla County Bearing object to the south face of a railroad tie fence post.

Location & Comments:

Compass Declination:

19° East

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1988
PAUL W. P. TOMKINS
2360

renews 6/30/04

6/30/02

Firm/Agency: **Tomkins Land Surveying, Inc.**
20 E. Poplar, Suite 204
Walla Walla, WA 99362

Party Chief: **Bryan Martin**

Notes: **Bryan Martin**

Witness: **Eric Flowers**

orlcr6N35ER9.doc

03-23-C