

Q-514-B 3N295BCD

City Planning Supervision Valuation Surveying Reports Designs

## C. H. Storms & Associates

CONSULTING ENGINEERS
REGISTERED WASHINGTON, OREGON

C. H. STORMS
Phone 4692-W
G. M. NEWBILL
Phone 2982-M
GEO. LAUBACK
B. F. CHAPMAN
J. O. BICKFORD, Jr.
E. BUCKNER

TELEPHONE 4170 304 Denny Building WALLA WALLA, WASH.

FILE

FIELD NOTES

OWNER: Wm. Bohns

TYPE OF SURVEY: Boundary

LOCATION: Section 5, Township 3 North, Range 29 EWM

Having found the 11 iron pipe marking the N1 Corner of Section 5, Township 3 North, Range 29 EWM and a rock marking the NW Corner of said Section 5, I then set an iron pin marking the center of Said Section 5. The iron pin marking the senter of said Section 5 was set by using ties given by previous survey and descriptions from iron pin found at the point of intersection of the East and West centerline of said Section 5 and the Westerly line of the right-of-way of the OWR & N Railroad Company. With these points located, I proceeded to set iron pins as shown on accompanying plat.