X-13

History of original corner establishment:

Corner established in 1882 by Herman D. Gradon under contract No. 452 5" diam. Tamarack at Corner, marked 1/4S on West face Tamarack, 5" diam., S.45°E., 9 links, marked 1/4SBT Tamarack, 5" diam., N.40°W., 13 links, marked 1/4SBT

Note: No restoration notes appear in county records

TIS R36E 1/4 S33 | S34 RPLS 1910 1982

Description of corner evidence found:

Found axe work on old burned face, which I took to be the Southeast bearing tree.

C.J. MARTIN SURVEYING

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Auton J. Martin

OR E GON
JULY 18, 1980

CLAYION-JESSE MARTIN
1910

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2%" diam. brass cap in a 2"X30" iron pipe at record bearing and distance from bearing tree.

Cap Stamped T1S R36E 1/4 S33 | S34 T RPLS 1910 BT 1982

8"D.B.H. Tamarack, N.55%"W., 24.4', scribed %S33BT 10" D.B.H. Tamarack, N.22°E., 33.3', scribed %S34BT Both B.T's. have a brass washer marked RPLS 1910, between the B&T, B.T. tags, attention signs and red painted bands
Steel fence posts 4.0'+ North and South with attention, monument and boundary signs attached.

Office of Surreyou County of Sandular State of Old of the State of Old of the State of State

Form R6-7100-57 (9/71)

GPO-798-276

92-108-R