

OREGON CORNER RESTORATION FORM

Section 31 Township 3N Range 28E
 County Umatilla Date: 06-20-02

Corner Designation: 3N28Z1


_____x_____	Condition Report Only
_____	Not Found
_____	Remonumented
_____	Unrecorded
_____	Surveyed In
_____	Referenced Out

Previous Renewals / Surveys, etc.

Survey 90-53-A records setting a brass capped monument here.
 Survey 91-34-B found that monument in a monument case.

Monument and Accessories Found: (condition and source)

Found the brass capped monument in a monument case in the pavement on the southwest side of Highway 207.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.

Made GPS tie to TRI Station Stanfield East Base.	Oregon State Plane Coord. - North Zone
Latitude 45°41'24.64038" N	Northing 739738.80
Longitude 119°22'21.38958" W	Easting 8490187.53
NAD 83 (1991)	Ortho Height 801.68
	Ellipsoidal Height 732.22

Location and Comments

Compass Declination
20°E

Surveyors Seal

The corner is located in a water valve case on the northwest side of Highway 207 at the junction with Saylor Road.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

RECEIVED BY:

Firm / Agency

David L. Haddock

Date: 2-02
 Rec'd By: KK
 No. 02-187-9

Haddock Surveying
 P. O. Box 1574
 Pendleton, OR 97801
 (541) 276-2174

OREGON
 JULY 12, 1968
 DAVID L. HADDOCK
 852

RENEWS 6-30-03