T 2N. R 32E. . W.M.

Corner Code No. P-1
Note: Konument marked as shown below

History of original corner establishment:

Corner was priginally set by Josiah A. Burnett, under Contract No. 98, dated September 12, 1880. At which time he set a charred stake, and raised a mound and trench, for the 174 corner to \$24 T2N R31E and \$19 T2N R32E.

In 1950, Bonneville Power Administration noted an old fence intersection as the 1/4 corner on their Transmission Line Maps.

D/AGRAM R31E T2N R32E 1 (4 R32E 1 (4 S19 1973 PLS 1106

Compass Declination: 18.0°

Description of corner evidence found:

Found an old fence corner and a 1/2" iron pin (origin of pin is unknown). Existing fences run North and West.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2 1/2" brass cap on a 1 1/4" by 30" galv. iron pipe, 30" in ground, and surrounded with a mound of earth. New monument was set at the position of the 1/2" iron pin. Buried the 1/2" iron pin in new mound. Set a steel fence post 2' West of the corner with a Witness corner sign attached.

New bearing objects: A 5/8" x 30" iron pin bears N 0 1/2° W - 19.7 feet. A 5/8" x 30" iron pin bears N 71° E - 26.3 feet. (Buried 14" below ground). A 5/8" x 30" iron pin bears S 57 1/2° E - 30.3 feet. (Buried 12" below ground). A 5/8" x 30" iron pin bears N 85° W - 24.1 feet.

All pins are capped with a 1 1/2" yellow plastic cap marked "W.R.WELLS, PLS 1106". Bearing Object signs are wired to each pin.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will: R. Wells
OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

expires 12/31/94

Form R6-7100-57 (9/71)

# GPO-798-276

93-54-(