History of original corner establishment:

The original corner was established by Daniel Chaplin on November 19, 1864, under GLO contract No. 107, as follows:

Set a stone, 20"  $\times$  8"  $\times$  6", for the 1/4 section corner.

DIAGRAM

T2S R31E 1/4 S15 S14 PLS 1636 1997

## Description of corner evidence found:

Found the corner stone plainly marked "1/4". The stone is lying loose on the southerly edge of a mound of stones, and is 20" x 12" x 4".

## Description of monument and accessories I established to perpetuate the original location of this corner:

In place of the stone, I set a  $1\ 1/2$ " x 30" iron pipe 17" into the ground to bedrock. A  $2\ 1/2$ " brass cap attached is marked as shown in the diagram above. I bury the corner stone along the north side of the pipe monument and build a mound of stones around the pipe to the cap, from which:

A 5/8" x 24" iron rod, set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 S14 NE", attached at ground level, bears N40 E. 90.2 feet.

N40 E, 90.2 feet.

A 5/8" x 24" iron rod, set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 S14 SE", attached at ground level, bears S3 E, 81.2 feet.

S39E, 81.2 feet.
A 5/8" x 24" iron rod, set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 S15 SW", attached at ground level, bears S37W, 130.1 feet.

S37-W, 130.1 feet.
A 5/8" x 24" iron rod, set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 S15 NW", attached at ground level, bears N47-30'W, 95.9 feet.

Form R6-7100-57 (9/71)

(COUNTY OFFICIAL)

HICKIVED BY

(DEPUTY)

GPO-791-311

Uzeelilla County Surveyor
Date 4-97
Rod & Sy Al