Guide Meridian between Ranges 30 and 31 E.

hains	Land, gently rolling. Grass hills.
	Soil, 2nd rate.
	August 4, 1859.
	5th Mile
	North between secs. 7 and 12.
	Var. 20° 15' East.
40.00	Set post for ½ sec. corner and build mound of earth with
	pits, trench &c as per instructions.
80.00	Set post for corner to secs. 6, 7, 1 and 12 and build
	mound of earth with pits, trench &c as per instructions.
	Land, 2nd rate, gently rolling. Grass hills.
	August 4, 1859.
	6th Mile
	North between secs. 1 and 6.
	Var. 18° 45' East.
40.00	Set post for \frac{1}{4} sec. corner and build mound of stone.
80.00	Set post for corner to Townships 1 and 2 North of Ranges
	30 and 31 East and build mound of earth with pits,
	trench &c as per instructions.
	Land, gently rolling. Grass hills.
	Soil, 2nd rate.
	NoteThe quality of the Land in Townships No. 1 North
	of Ranges 30 and 31 East is good, 2nd rate prairie.
	There is no timber in either Townships. There are
	three good springs in T. 1 North, Range No. 31 East.
	Both Townships should be subdivided.
	August 4, 1859.
	T. 1 N., R. 30 E. (Exteriors) Surveyed by David P. Thompson under contract No. 83 Dated July 22, 1859.
	Begin at the post, the established corner to Townships 1