		Subdivisions of T. 3 N. R. 30 E.
	Chains	
		charred stake and raised mound with trench and pits, as
		instructions.
		A snow peak in Cascade range bears N. 58° W.
		A " " " " N. 73° W., from this
	İ	and the state of t
		section post.
		Land, gently rolling prairie.
	to	Soil, good, 2nd rate.
		East on a random line between Secs. 23 & 26.
	1	Variation 20° 45' E.
	40.00	Set a temporary quarter sec. post.
	80.70	Intersect N. & S. line at post corner to Secs. 23, 24, 2
		& 26.
		West on a true line between Secs. 23 & 26.
	40.35	Set a post for quarter section corner. Drove a charred
		stake and raised mound with trench and pits, as per
	1000	instructions.
	80.40	To a trail before noted, bears N.W.& S.E.
	80.70	The corner to Secs. 22, 23, 26 & 27.
	00.70	
	*	Land, gently rolling, nearly level prairie.
	1	Soil, good 2nd rate.
	200	- 10
		North between Secs. 22 & 23.
	2.50	To Indian Trail before noted, course N.W. & S.E.
	40.00	Set a post for quarter section corner. Drove a charred
		stake and raised mound with trench and pits, as per
		instructions.
	80.00	Set a post for corner to secs. 14, 15, 22 & 23. Drove
		charred stake and raised mound with trench and pits,
	77 . 10	per instructions.
		Land, gently rolling prairie, slightly descending to the
		North.
	-	Soil, good 2nd rate.