Sub-Subdivisions of T. 3 North, R. 34 East

		Bab-Babatvisions of 1. 0 horon, n. of 2000
	Chains 39.96	Deposited charred stake 12 ins. in the ground for 1/16
		sec. cor. Dug pits 18x18x12 ins. E. and W. of stake,
		$5\frac{1}{2}$ ft. dist. Raised mound of earth $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
)		ft. base over it, and in E. pit drove stake, 2 ft.
		long, 2 ins. square, 12 ins. in the ground, marked
		1/16 S on N. face.
	59.94	Deposited charred stake 12 ins. in the ground, for 1/16
		sec. cor. Dug pits 18x18x12 ins. E. and W. of stake,
		$5\frac{1}{2}$ ft. dist. Raised mound of earth $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
	· •	ft. base over it, and in E. pit, drove stake 2 ft.
		long, 2 ins. square, 12 ins. in the ground, marked
		1/16 S on N. face.
	79.92	To point of beginning.
	79.92	Section Control Section 1900 Se
		Land, level.
		Soil, good. All cultivated.
	į – Į	East on random through Center of Sec. 1.
'		Va. 21° East.
		Beginning at $\frac{1}{4}$ sec. cor. bet. Secs. 1 and 2. Set tem-
	e	porary cors. at 20, 40 and 60 chains, and at
	79.90	Intersect E. bdy. at ½ sec. cor. Thence West on true
		line.
	19.98	
		sec. cor. Dug pits 18x18x12 ins. E. and W. of stake,
		$5\frac{1}{2}$ ft. dist. Raised mound of earth $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
		ft. base over it, and in E. pit drove stake 2 ft.
		long, 2 ins. square, 12 ins. in the ground, marked
		1/16 S on N. face.
	39.95	
		(a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
	€:	cor. Dug pits 18x18x12 ins. E. and W. of stake, 52
	S# 20*	ft. dist. Raised mound of earth la ft. high, 32 ft.
		base over it, and in E. pit drove stake 2 ft. long, sq.,12 ins.
	EO 06	2 ins./in the ground, marked & S on N. face.
	59.92	Deposited charred stake 12 ins. in the ground for 1/16
		sec. cor. Dug pits 18x18x12 ins. E. and W. of stake,
		$5\frac{1}{2}$ ft. dist. Raised mound of earth $1\frac{1}{2}$ ft. high, $3\frac{1}{2}$
		3g 1t. dist. Raised mound of earth 1g ft. high, 3g