	Neuth Ponge 35 Rest.
Chains.	Sub Subdivision of Township 3 North Range 35 East.
Charms.	over it. And in E. pit drove stake 2 ft. long 2 ins.
12	square 12 ins. in the ground marked 1/16 S. on N.face.
37.08	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits $18x18x12$ ins. E, & W. of stake $5\frac{1}{2}$
	ft. dist. raised mound of earth $1\frac{1}{2}$ ft. high $3\frac{1}{2}$ ft.
320	base over it. And in E. pit drove stake 2 ft. long 2
	ins. square 12 ins. in the ground marked 1/16 S. on
	N. face.
57.08	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits 18x18x12 ins. E. & W. of stake 51
-	ft. dist. raised mound of earth $1\frac{1}{2}$ ft. high $3\frac{1}{2}$ ft.
	base over it. And in E. pit drove stake 2 ft. long 2
5 F	ins. square 12 ins. in the ground marked 1/16 S. on
	N. face.
77.08	To point of beginning.
18	Land level.
10	Soil 1st rate.
sg s	Not cultivated.
	West on random through Center of Sec. 30.
	Va. 21° East.
N 80	Began at 1 Sec. cor. of Secs. 29 & 30.
	Set temporary cors. at 20, 40 and 60 chains. And at
77.12	Intersect W. Bdy. 25 lks. N. of & Sec. Thence
47	N. 89° 49' E. on true line.
17.12	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits 18x18x12 ins. E. & W. of stake 51
	ft. dist. raised mound of earth 12 ft. high 32 ft.
9.5	base over it. And in E. pit drove stake 2 ft. long 2
	ins. square 12 ins. in the ground marked 1/16 S. on
8	N. face.
37.12	Deposited charred stake 12 ins. in the ground for $\frac{1}{4}$ Sec.
	cor. Dug pits 18x18x12 ins. E. & W. of stake 51 ft.
	dist. raised mound of earth 12 ft. high 32 ft. base
9 10	over it. And in E. pit drove stake 2 ft. long 2 ins.
	square 12 ins. in the ground marked & S. on N.face.
lance and	