	그 등 기계 및 기계
t .	Sub Subdivision of Township 3 North Range 35 East.
Chains 17.30	Deposited charred stake 12 ins. in the ground for 1/16
9	Sec. cor. Dug pits 18x18x12 ins. E. & W. of stake 52
0 1	fft dist. raised mound of earth $1\frac{1}{2}$ ft. high $3\frac{1}{2}$ ft.
	base over it. And in E. pit drove stake 2 ft. long 2
Page.	ins. square 12 ins. in the ground marked 1/16 S. on N
	face.
37.30	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits $18x18x12$ ins. E. & W. of stake $5\frac{1}{2}$
. 11	ft. dist. raised mound of earth 12 ft. high 32 ft.
	base over it. And in E. pit drove stake 2 ft. long 2ins
	square 12 ins. in the ground marked 1/16 S. on N. face
57.30	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits 18x18x12 ins. E. & W. of stake 51
	ft.dist. raised mound of earth 12 ft. high 32 ft.base
	over it. And in E. pit drove stake 2 ft. long 2ins.
	square 12 ins. in the ground marked 1/16 S. on N.face.
77.30	To point of beginning.
	Land level, mostly,
	Soil good.
8.	
	West on random through Center of Sec. 6.
	Va. 20° East.
	Began at \(\frac{1}{4}\) Sec. cor. bet. Secs. 5 & \(\frac{6}{2}\).
	Set temporary cors. 20, 40 and 60 chains. And at
77.28	Intersect E. bdy. 21 lks. N. of 4 Sec. cor. Thence
	N. 89° 51' East on true line.
1.00	Wagon road N. & S.
17.28	Deposited charred stake 12 ins. in the ground for 1/16
	Sec. cor. Dug pits 18x18x12 ins. E. & W. of stake 51
	ft. dist. raised mound of earth la ft. high 32 ft.
3	base over it. And in E. pit drove stake 2 ft. long 2
	ins. square 12 ins. in the ground marked 1/16 S. on
	N. face.
F =	
11	