Tô	hains	
		By lining both ways with opposite 1/16 cors., I placed a
		2 x 2 ins. stake mkd. 1/16 as center SE4
		Ran on line
		N. 0° 20' E. from SW cor. SET SET to NW cor NET SET
	10.00	Set 2 x 2 ins. stake as NE cor. Farm Unit M. on line.
	10.00	And the second s
	20.00	Center SE
	30.00	Set flag to give direction to N. Bdy. Farm Unit H on line.
	40.00	1/16 corner.
	- 1	
		Ran on line bet. NE cor. SEE SEE and NW cor. SWE SEE
		N. 89° 57' W. from NE cor. SE4 SE4
	20.04	Center SE
	30.06	Set 2 x 2 ins. stake on line as SE cor. Farm Unit E.
	39.99	Meander cor. center O. R. & N. track.
	40.08	1/16 corner.
-		
		Ran on line bet. NW cor. SW SE and NW cor SW SW
8		N. 89° 57' W.
	1.74	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.
	10,02	Set 2 x 2 ins. stake on line as SW cor. Farm Unit G.
	20.04	Set 2 x 4 ins. stake on line as center SW4
	40.08	1/16 corner.
	- 12	Ran on line bet. the SW cor. SE SW and NW cor NE SE
70		N. 0° 6' E. from SW cor. SE4 SW4.
	20.00	Center SW4
1	40.00	1/16 corner.
	(a)	The flag set to give direction to the W. Bdy. of Farm
- 1	=0,4	Unit G. SW4, being visible from the SW cor. of Farm Unit
	- 1	G, I ran
	_	N. 0° 9' E. along W. Bdy. of Farm Unit G from its SW cor.
	12 22	
	13.33	Set 2 x 2 ins. stake mkd. W C as witness cor.
	16.21	Meander cor. center O.R. and N. Track.

40

KILMAN 1967