Chains		Fee
	_Section 15	
N .	The \(\frac{1}{2}\) cor. bet. secs. 14 & 15 and \(\frac{1}{2}\) cor. bet. secs. 15	
1.4	and 16 being intervisible, I ran	1
	N. 89° 34' W. along this & line from the & Cor. bet. Secs.	
	14 and 15.	
20.00	Set trial 1/16 cor. on line as SW cor. SE4 NE4.	
28:85	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.	
30.46	Meander cor. center O. R. and N. Erack.	
32.18	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.	
39.89	Center of sec.	
59.89	Set trial 1/16 cor. on line as NW cor. of NE SW	7.9
80.07	\$ Cor. bet. secs. 15 & 16	
i.e.	Set 2 x 2 ins. stake mkd. 1/16 as SW cor. SE2 NE2 in its	
	proper position, that is, 19.94 chs. from \$2 cor. bet.	
	secs. 14 & 15.	
	Set 2 x 4 ins. stake mkd. 1/16 as NW cor. of NE2 SW2 on	j
	line in its right position, 20.09 chs. from \(\frac{1}{2}\) cor. bet.	
	secs. 15 & 16.	
- FR	3668. 15 d. 10.	
	By lining in both ways with opposite 1/16 cors. I set 2 x	
	# ins. stake mkd. 1/16 at center of NE4	100
	Ran	
	N. 0° 03' W. from SE. cor. Farm Unit K along E. Bdy. of	
	Farm Unit K.	
10.11	Set trial flag on line to give direction of N. Bdy. of	
	Farm Unit M.	
20.00	Enter NE2.	
20.00	Trial flag being in correct position was not moved.	
12 2	Training being in correct position was not moved.	
4 40	The NW con of Ferm Init I being wishle from contact of No.	
100	The NW.cor. of Farm Unit L being visible from center of NE	•
3 32	2004	
,	N. 89° 34' W. along N. Bdy. Farm Unit K from center of NE	•
1.32	Set 2 x 2 ins. stake mkd. W C on line as witness cor.	
3.88	Meander cor. center O. R. & N. track.	
5.88	Set 2 x 2 ins. stake mkd. W C on line as witness cor.	