Subdivisional Lines of T. 4 N., R. 34 E., W.M

	Chains.	ti II	Feet
		and raised mound as per instructions.	
7,0	80.20	To post Cor.	
		Land; 2nd rate.	1
			1
		N. bet. Secs. 14 & 15	1
	40.00	Set post Cor. for 1/4 Sec.; drove charred stake, dug pits	
		and raised mound as per instructions.	
	80.00	Set post Cor. for Secs. 10, 11, 14 & 15; drove charred	
		stake, dug pits and raised mound as per instructions.	
E (18)		Land; rolling	
		= 11 g/1 m	
		Soil; 2nd rate.	

		E. on random bet. Secs. 11 & 14 Var. 20° E.	
	40.00	Set temp. & Sec. post Cor.	
40	80.26	Intersect N. & S. line, 15 lks. S. of pest.	
		S. 89° 54' W. on true line	
	40.13	Set post Cor. for & Sec. Cor.; drove charred stake, dug	
	10.10	pits and raised mound as per instructions.	
	80.26	To post Cor.	
		Land; broken, good grass.	
		Soil; 2nd rate.	
		N. S. C.	
		N. bet. Secs. 10 & 11	
	40.00	Set post Cor. for & Sec.; drove charred stake, dug pits	,
	-> >-	and raised mound as per instructions.	
	80.00	Set post Cor. for Secs. 2, 3, 10 & 11; drove charred st	ake,
		dug pits, and raised mound as per instructions.	
		Land; rolling, good grass.	
		Soil; 2nd rate.	
	ħ.	E. on random bet. Secs. 2 & 11	
		Var. 20° 30' E.	1
	40.00	Set temp. ½ Sec. post Cor.	
	80.22	Intersect N. and S. line, 19 lks. S. of post Cor.	
		S. 89° 52' W. on true line	
	40.11	Set post Cor. for 1/4 Sec.; drove charred stake, dug pit	
7		and raised mound as per instructions.	
EC	80.22	To post Cor.	
	30.22	Land; rolling, good grass.	