Subdivisional Lines of T. 4 N., R. 34 E., W.M.

	Chains		Feet
		E. on random bet. Secs. 30 & 31	
0	40.00	Set temp. 1 Sec. post cor.	
	80.08	Set temp. } Sec. post cor.	
	40.08	Intersect N. and S. line, 22 lks. S. of post Cor.	
	- 04	S. 89° 51' E. on true line	
	40.08	Set post Cor. for \(\frac{1}{4} \) Sec.; drove charred stake, dug pits	-
		and raised mound as per instructions.	
	80.08	To post cor.	
		Land; rolling, good grass.	
5		Soil; 2nd rate.	
		N. bet. Secs. 29 & 30	
	40.00	Set post cor. for 4 Sec.; drove charred stake, dug pits	
	The state of the s	and raised mound as per instructions.	
	80.00	Set post cor. for Sec. 19 & 20, 29 & 30; drove charred sta	ika
	CONTRACTOR OF THE PARTY OF THE	dug pits and raised mound as per instructions.	,
		Land; rolling, grass excellent	
	2,01	Soil; 2nd rate.	
		E. on random bet. Secs. 20 & 29	
		Var. 21° E.	
	40.00	Set temp. 1 Sec. Cor.	
	40.00 79.47	Set temp. ½ Sec. Cor. Intersected N. and S. line, 36 lks. N. of post Cor.	
		Intersected N. and S. line, 36 lks. N. of post Cor.	
	79.47	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line	
	79.47	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for \(\frac{1}{4} \) Sec.; drove charred stake, dug pits	
	79.47	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line	
	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for \(\frac{1}{4}\) Sec.; drove charred stake, dug pits and raised mound as per instructions.	
	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor. Land; rolling, grass excellent	
	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor.	
	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor. Land; rolling, grass excellent Soil; 2nd rate.	
	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor. Land; rolling, grass excellent Soil; 2nd rate. W. on random bet. Secs. 19 & 30	_
	79.47 39.73 79.47	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor. Land; rolling, grass excellent Soil; 2nd rate. W. on random bet. Secs. 19 & 30 Set temp. ½ Sec. post cor.	
Se.	79.47 39.73	Intersected N. and S. line, 36 lks. N. of post Cor. N. 85° 45' W. on true line Set post cor. for ½ Sec.; drove charred stake, dug pits and raised mound as per instructions. To post cor. Land; rolling, grass excellent Soil; 2nd rate. W. on random bet. Secs. 19 & 30	