Chains	
	E. on random bet. Secs. 21 & 28
	Var. 21° E.
40.00	Set temp. 4 Sec. Cor.
80.32	Intersected N. & S. line, 21 lks. S. of post Cor.
00.00	S. 89° 51' W. on true line
40.16	Set post Cor. for & Sec.; drove charred stake, dug pits
10.10	and raised mound as per instructions.
80.32	To post Cor.
00.02	Land; rolling, good grass
	Soil; good 2nd rate.
	Soll, good and rate.
	W hat 02-2 00 101
40.00	N. bet. Secs. 20 & 21
40.00	Set post Cor. for 1 Sec.; drove charred stake, dug pits
00.00	and raised mound as per instructions.
80.00	Set post Cor. for Secs. 16, 17, 20 & 21; drove charred
	stake, dug pits and raised mound as per instructions.
	Land; rolling, good grass
	Soil; good 2nd rate.
-	
	E. on random bet. Secs. 16 & 21
	Var. 21° 30' E.
40.00	Set temp. & Sec. Cor.
80.17	Intersected N. & S. line, 27 lks. S. of post Cor.
E 50	S. 89° 48' W. on true line
40.08	Set \(\frac{1}{4} \) Sec. post Cor.; drove charred stake, dug pits and
200000 800000	raised mound as per instructions.
80.17	To post Cor.
- 4.6	Land; rolling, good grass
	Soil; 2nd rate.
	N. bet. Secs. 16 & 17
40.00	The control of the co
23.00	Set post Cor. for \$\frac{1}{4}\$ Sec.; drove charred stake, dug pits and raised mound as per instructions.
78.00	Road, course E. & W.
10,000 A	
80.00	Set post Cor. for Secs. 8, 9, 16 & 17; drove charred stake