Subdivision Sec.28, T 5 N R 28 E W M.

Chains	
14.17	Stake from which SE.Cor. of Sec. brs. S.08°11'W., 26.51 chs.
12 12	The E. line of Sec.is; s therefore as follows:
	Beginning at SE. Cor. of Sec. marked as heretofore describ-
	ed, thence N.O°O4' W.
39.88	W. (1/4) quarter Sec. Cor. marked as heretofore described.
79.76	NE. Cor. of Sec. marked as heretofore described.
	All section and (1) quarter section Cors. in the section
	being now in place, I proceed to subdivide the section as follows:
,e: 1	It being impracticable to chain through on E. & W. center
	line of Sec., because of the rocky cliffs of Umatilla
	Butte before mentioned, and not necessary, I establish
	said E. & W. center line in oreder to make intersection
	of same with N. & S. center line, by double centering
86 S	between E. & W. (1) quarter Sec. Cors., flags on same bein
	being visible from high ground.
175	I then proceed to run N. & S. wenter line of Sec. as follows:
	CONTRACTOR OF THE SECOND CONTRACTOR OF THE SEC
	From the S.(1/4) quarter Sec. Cor., a lava rock, 3 ins. x 6
	ins., set in ground and projecting 4 ins. above, no wit-
	nesses being now in evidence because of changes, develop-
\$0047	ment and traffic, I sight to the N. (4) quarter Cor. on
	which flag is visible and run random line N.0°09'W.
	(in road).
19.97	Find post, 4 ins. x 4 ins., projecting 10 ins. above ground
	for 16/16 Cor.
39.94	Intersect E. & W. center line of Sec. and set stake for
20 E	16/13 Cor.
59.91	Set stake for 16/10 Cor.
79.88	N. (1) quarter Cor. Sec. 28, now marked by an iron pipe,
	l in. diam. flush with surface of roadway, in place of
	and accepted as original Cor. in settled and developed
	region, witness mounds being how obliterated by road