Subdivisional Lines, T 5 N R 31 E W M.

	H A
Chains	
40.30	Drove charred stake; raised mound of earth, with pits, etc.,
	as per instructions, for 4 Sec. Cor.
80.60	The Cor.
1	Land; rolling.
	Soil; 1st rate. Good grass.
-	4 (4)
	N. bet. Secs. 16 & 17.
	Var.21°15'E.
40.00	Drove charred stake; raised mound of earth, with pits, etc.,
	as per instructions., for \(\frac{1}{2} \) Sec. Cor.
80.00	Drove charred stake; raised mound of earth, with pits, etc.,
	as per instructions, for Cor. to Secs. 8, 9, 16 & 17.
	Drove alder stake, 2 ft. long, 2 ins. sq., in S.E. pit.
	Land; rolling.
#2.	Soil; 1st rate. Good grass.
	E. on random line bet. Secs. 9 & 16.
40.00	Set temp. 1 Sec. Cor.
80.58	Intersect N. & S. line, 20 lks. N. of Cor.
	N.89°49° W. on true line.
40.29	Drove charred stake; raised mound of earth, with pits, etc.,
	as per instructions, for \(\frac{1}{4} \) Sec. Cor.
80.58	The Cor.
	Land; gently rolling.
56	Soil; 2nd rate, good grass.
M 51.5	W hat Same S to O
	N. bet. Secs. 8 & 9.
40.00	Drove charred stake & raised mound of earth, with pits, etc.,
	as per instructions, for & Sec. Cor.
80.00	V 5 3 3 3 3 3 4 5 5 7 3 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7
	as per instructions, for Cor. to Secs. 4, 5, 8 & 9.
-	Drove willow stake, 2 ft. long, 2 ins. sq., in S.E pit.
	Land; gently rolling. Soil; 2nd rate.