Subdivisional Lines, T 5 N R 33 E W M.

	Chains	
		Land; broken.
		Soil; 2nd rate. Grass good.
	2	N. bet. Secs. 7 & 8.
		Var.21°E.
	40.00	Set & Sec. post. Drove charred stake; dug pits and raised mound, as per instructions.
	80;00	Set post Cor. for Secs. 5, 6, 7 & 8. Drove charred stake;
		dug pits and raised mound, as per instructions.
		Land; rolling.
42		Soil; 2nd rate. Grass good.
020	1.	
		E. on random bet. Secs. 5 & 8.
		Set temp. ½ Sec. post.
	80.10	Intersect N. & S. line, 50 lks. S. of post, from which
		I run
		S.89°38' W. on true line.
	40.05	Set & Sec post. Drove charred stake; dug pits and raised
		mound, as per instructions.
	80.10	To post Cor.
		Land; rolling. Grass good. Soil; 2nddrate.
		8
		W. on random bet. Secs. 6 & 7.
	40.00	Set temp. & Sec. post.
	80.45	Intersect N. & S. Tp. line, 40 lks. S. of post, from which,
		I run
		S.89°43'E.
	40.45	Set & Sec. post; drowe charred stake; dug pits and raised
		mound, as per instructions.
	80.45	To post Cor.
	=	Lend; broken.
		Soil; 2nd rate. Grass good.

KILMAN 1987