Subdivisional Lines, T 5 N R 34 E W M.

Chains	12. Ž 12.
	N. bet. Secs. 8 & 9.
40.00	Set & Sec. post, in ravine. Drove charred stake; dug pits
	and raised mound, as per instructions.
80.00	Set post Cor. for Secs. 4, 5, 8 & 9.
00.00	
	Drove charred stake; dug pits and raised mound, as per instructions.
7.4%	
	Land; broken.
	Grass good.
	Soil; 2nd rate.
	April 15th.
	E. on random bet. Secs. 4 & 9.
40.00	Set temp. 2 Sec. post Cor.
80.06	Intersect N. & S. line, 42 lks. S. of post, from which, I
20 To 1	run
	S.89°42'W. on true line.
40.03	Set & Sec. post.
72 1 14	Drove charred stake; dug pits and raised mound, as per.
	instructions
80.06	To post Cor.
00.00	Land; quite broken.
	Control Contro
	Soil; good 2nd rate.
#1 D.	N. on random bet. Secs. 4 & 5.
40.00	Set temp. 4 Sec. post.
80.46	Intersect N. Tp. line, 52 lks. E. of post, from which, I
	run - r
100	S.22' E. on true line.
40.46	Set 1 Sec. post. Drove charred stake; dug pits and raised
40.40	2
	mount, as per instructions.
	Land; very broken.
	Grass good.
	Soil; 2nd rate.