



NARRATIVE

The purpose of this survey was to establish the East line of a parcel belonging to John K. and Mary Leber as recorded on Roll 157, Pg 514, Deed Records.

The control for this survey was the $\frac{1}{2}''$ i. pins shown as found on the Gross Monument of NE 5th and Mill St.. The bolt on the North right-of-way line of SE 3rd Ave. has no record but it fits the centerline alignment of SE 3rd Ave. extended N $65^{\circ}00'00''$ E.

The deed calls for the TP08 to be on centerline and 447.1 feet from the Easterly right-of-way of Mill St.. As shown there is a discrepancy between bearings called for in the Kolberg tract and the East line of Tract I as called for in Roll 157, Pg 515. I found a $\frac{1}{2}''$ iron rebar, $\frac{1}{2}''$ smooth iron bar and $\frac{1}{4}$ O.D. iron pipe as shown. The $\frac{1}{4}''$ i. pipe and $\frac{1}{2}''$ rebar appear to be established property corners, as testified to by neighbors and were held. The $\frac{1}{2}''$ smooth iron bar does not appear to relate to any of the lines so I did not use it. To establish the Southwest corner of the parcel I intersected a line between the $\frac{1}{4}$ O.D. i. pipe and the $\frac{1}{2}''$ i. rebar with the East line of Tract I as established from the deed calls. The Northwest and Northeast corners of the tract was established at the deed distances. The house is then a foot West of the property line. Bearings are based upon SE. Mill St. being N $25^{\circ}00'00''$ W as shown.

KRUMBEIN ENGINEERING LTD. ENGINEERS - SURVEYORS - PLANNERS 301 S.E. Second Pendleton, Oregon		1/30' MID 69-71C 6-24-00 DUE 69-28
Survey for LEBER		PROVED BY D. H. K. L. R. G. 3-90 K.A. R.G. 90-16-B
SE 4, SW 1/4, Sec. 1, T50, R.35E, W.M.		