## NARRATIVE OF SURVEY

THE PURPOSE OF THIS SURVEY WAS TO MONUMENT PORTIONS OF THE BOUNDARIES OF FOUR PARCELS OF LAND WHICH WILL BE REDEFINED FROM FOUR EXISTING TAX LOTS. THE "BOUNDARY LINE ADJUSTMENTS", DESCRIPTIONS AND MAP ARE TO BE SUBMITTED TO THE UMATILLA COUNTY PLANNING DEPARTMENT FOR APPROVAL.


SECTION LINES AND BREAKDOWN LINES WITHIN SECTIONS 10 AND 11 WERE NOT RETRACED AND REMONUMENTED ON THIS SURVEY. THEREFORE, CALLS TO SECTION AND SECTION BREAKDOWN LINES ARE GIVEN IN A "MORE OR LESS" MANNER. STATE HIGHWAY MAP TIES TO THE WEST 1/4 CORNER OF SECTION 11 WERE USED TO REESTABLISH AND REMONUMENT THIS CORNER. THE REDEFINED PARCELS ARE TIED TO THIS REMONUMENTED CORNER.

SUFFICIENT MONUMENTATION OF THE RIGHT-OF-WAY OF STATE HIGHWAY 30 WAS FOUND TO ESTABLISHED RIGHT-OF-WAY LOCATIONS THROUGHOUT THE SURVEYED AREA. MANY OF THE STATE HIGHWAY MONUMENTS HAVE BEEN DESTROYED BY FARMING OPERATIONS, AND SEVERAL CONCRETE MONUMENTS WERE FOUND LOOSE IN WORKED FIELDS.

THE THREE 1/2 INCH IRON PINS FOUND ON THE SOUTHWEST PORTION OF THE PROPERTY APPEAR TO HAVE BEEN ESTABLISHED BY A SURVEYOR BECAUSE OF THERE RELATIONSHIP TO A PORTION OF THE DEED DESCRIPTION. THE SAME SURVEYOR MUST HAVE WRITTEN PORTIONS OF THE DEED DESCRIPTION. ALTHOUGH NO RECORD WAS FOUND FOR THE PINS IN THE COUNTY SURVEYOR'S OFFICE, I ACCEPTED THE OBSERVED LOCATION OF THESE PINS AND INCORPORATED THEM INTO THE PRESENT SURVEY. I DO NOTE THAT THE PERSON ESTABLISHING THESE PINS AND PREPARING PORTIONS OF THE DEED DESCRIPTION ROTATED THE THETA ANGLE BETWEEN TRUE AND GRID NORTH IN THE WRONG DIRECTION, RESULTING IN DEED BEARINGS IN THIS AREA BEING APPROXIMATELY 3 DEGREES OUT OF ALIGNMENT WITH TRUE NORTH.


THE PRESENT SURVEY WAS MADE WITH A TWO PERSON CREW USING A LIETZ 1 SECOND AUTOMATIC TOTAL STATION. BASIS OF BEARINGS IS A SOLAR OBSERVATION AS NOTED ON THIS PLAT.

NOTE: THAT PORTION OF THE NORTHEAST 1/4 OF SECTION 10 LOCATED EAST OF THE EASTERLY RIGHT-OF-WAY LINE OF STATE HIGHWAY NO. 11 HAS NOT BEEN CONVEYED TO THE WINNS BY DEED DESCRIPTION. THE WINNS ARE NOW IN THE PROCESS OF ACQUIRING THESE LANDS.



DETAIL OF PARCEL 2

SCALE 1" = 100"



## LEGEND

- - SET 5/8" BY 30" IRON ROD WITH 1 1/2" YELLOW PLASTIC CAP MARKED "W.R. WELLS - PLS 1106".
- ← STATE HIGHWAY DEPARTMENT RIGHT-OF-WAY MONUMENT. FOUND 5/8" IRON PINS UNLESS OTHERWISE NOTED.
- O OTHER MONUMENTS FOUND AS NOTED.
- ♠ RE-ESTABLISHED POSITION OF GLO CORNER AND REMONUMENTED WITH 2 1/2" BRASS CAP ON 1 1/2" BY 30" GALV. IRON PIPE. SEE CORNER RECORD FILED SEPARATELY ..
- ₩ EXISTING IRRIGATION RISER.
- (XOX)- RECORD FROM CORRECTION DEED RECORDED IN REEL 174, PAGE 1307, DEED RECORDS.

REGISTERED PROFESSIONAL LAND SURVEYOR

Willi R. Wells

OREGON

JULY 22, 1977 WILLIAM R. WELLS 1106

357 N.E. HWY. 11 P.O. BOX 1696 PENDLETON, ORE. 97801

2/15/91 CK. BY: WRW NO: 91-89

PROJECT: BOUNDARY LINE ADJUSTMENT FOR

RECEIVED BY

Na. 91-17-C

Rec'd By A

Umatilla County Surveyor

PRESTON AND ARLENE WINN LOCATED IN SECTIONS 10, AND 11, T4N, R35E, W.M., UMATILLA COUNTY, OREGON

WILLIAM R. WELLS, PLS

PHONE: (503) 276-6362

\WINN.DWG