FND. 1/2" I.R. SURVEY JONES PUNKIN CENTER ROAD N 89° 16' 40" E 1577,66 FND. IR. FND.1/2" 1.R. N 89° 16'40"E 152,00 267,04 240,00 1977 EDWARDS 0.8'50UTH 26.8' WE ST SURVEY FOR T.T. AND W IN JUNE OF 1978 I DISCOVERED AN ERROR IN THE COMPUTED BREAKDOWN OF SECTION FIVE WHICH WAS SUPPLIED BY WAYNE HARRIS COMPANY IN 1975. BETWEEN THOSE DATES, MANY SURVEYS WERE DONE USING THE ERRONIOUS INFORMATION. IN JAN. 1979, I CONDUCTED A SURVEY FOR TINDOL IN THE N.E. QUARTER OF SECTION FIVE AND DECIDED TO LEAVE THE SURVEYS IN THIS AREA AS IS BECAUSE MANY FENCES AND OR DEEDS WOULD HAVE TO BE CHANGED. THE NORTH QUARTER CORNER OF SECTION FIVE SHOULD BE APPROXIMATELY FIVE FEET EAST OF WHERE IT IS AT THIS TIME AND ALL PROPERTY LINES WOULD SHIFT EASTERLY APPROXIMATLY THE SAME AMOUNT, BUT I AM LEAVING THE SURVEYS AS IS BE-CAUSE OF THE ABOVE MENTIONED PROBLEMS. THE FIVE FOOT ERROR GETS PROGRESIVELY LESS FROM THE NORTH 1/4 CORNER TO THE N. W. CORNER OF SECTION 5. 267.66 S 89º 16' 40"W 703.92' N,0°58'57" FND. I.R. O.9' EASEMENT 703,51 229 WEST ROAD N.0° 53' 09" **REVISED 3-20-80** SE! 14 NE! 14 N.W. CORNER OF 40 N.W. 1/A SEC. S. 1977 DRIVER SURVEY FND. 1/2" I.R. (660.23) (660,23') \$88°58'42" W BEARING BASE 1977 DRIVER SURVEY FOR WILSON SURVEY FOR: ROBERT BOTTS FOR 1/2 IR's SEE 1978 SURVEY BY EDWARDS LOCATION: N.W. 1/4 SECTION 5, T4N, R29E,W.M. FOR WILSON REGISTERED UMATILLA COUNTY, OREGON PROFESSIONAL LAND SUPVEYOR DATE: 5 - 24 - 79 REVISED 3-20-80 SCALE: 1"= 100' RECEIVED BY OI/2"IRON RODS SET MONUMENTS FOUND Umatilla County Surveyor JOB NO. S. 7904105 OREGON Date 4-14-80 G. DENNIS EDWARDS EDWARDS SURVEYING P.O. Box 763 Rec'd By EL. S Hermiston, Ore. 567-3339 No. R-49-A