
## **OREGON CORNER RESTORATION FORM**

Section	23	Township	1N Range	32E	
County	Umatilla	_ Date:	June 29. 2009	0.2	
				X	_Condition Report Only
Corner Designation: 1N32P17					Not found
					Remonumented
Quarter corner common to sections 22 and 23,					Unrecorded
T1N, R32E, W.M., Umatilla County, Oregon.					Surveyed in
					Referenced out

Previous Renewals / Surveys, etc.

Corner originally set by Daniel Chaplin under contract #107 dated September 21, 1864. His record reads: Set post for 1/4 sec. cor. in mound of earth with charred stake, pits &c. as per instructions. In survey 02-161-B I set a 1"x24" iron rebar with a 2" aluminum cap at the intersection of county roads running north, south, and east.

Monument and Accessories found: (condition and source)
I found the aluminum cap and rebar from 02-161-B in good condition.



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None. This certificate is being filed to record the state plane coordinates shown below.

For references:

The monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments **Compass Declination** Surveyors Seal NAD 83/1991 State Plane Coordinate Oregon North Zone REGISTERED N = 691,785.05 ift **PROFESSIONAL** E = 8,640,932.93 ift Firm / Agency LAND SURVEYOR Witness Tree Surveying RECEIVED BY: Address Umatilla County Surveyor P.O. Box G OREGON Date: 6-10 Pilot Rock, Or. 97868 JULY 9, 2001 STEPHEN K. HADDOCK Rec'd By: Party Chief Stephen K, Haddock RENEWAL DATE 6-30-11