
OREGON CORNER RESTORATION FORM

| Section | 36 | Township | 1N | Range | 32E | |
|--|----------|----------|------------|-------|-----|-----------------------|
| County | Umatilla | _ Date: | June 29, 2 | 2009 | | : |
| Corner Designation: 1N32Z25 | | | | | x | Condition Report Only |
| Corner to Township 1 North, Ranges 32 and 33 East, | | | | | | Remonumented |
| Section 36, T1N, R32E and Section 31 T1N, R33E, | | | | | | Unrecorded |
| W.M., Umatilla County, Oregon. | | | | | | Surveyed in |
| | | | | | | Referenced out |

Previous Renewals / Surveys, etc.

Corner originally set by David P. Thompson under contract No. 79, dated July 26, 1858. His record reads: Set post for corner to Townships 1 North, Ranges 32 and 33 East. James Currin and James Noland under Special Instructions dated May 4, 1887 state: Set basalt stone, 16x14x10 marked SC with 6 notches on N., E. and W. edges. and raised mound of stone. Lincoln Wilkes in the 1917 survey for the Diminished Indian Reservation states: set an iron post, 3 ft. long, 2 ins. diam., with brass cap. Ron Scherler in a 1976 dependent resurvey states: Found a 2" iron post with brass cap with the section numbers reversed. Re-marked as shown.

Monument and Accessories found: (condition and source)
I found the Wilkes monument in good condition, marked as indicated by Scherler.



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None.

This monument was tied to report the Oregon State Plane, NAD 83/1991 coordinates only.

Measurements were made with a Trimble R7/R8 RTK GPS system.

Location and comments Compass Declination NAD 83/1991 State Plane Coordinate Oregon North Zone N = 678,749.88 ift E = 8,651,725.27 ift

Firm / Agency
Witness Tree Surveying
RECEIVED BY:
Umatilla County Surveyor
Date: 60 Pilot Rock, OR 97868
Rec'd By: KK Party Chief
No. 10-93-C Stephen K, Haddock

Surveyors Seal
REGISTERED

PROFESSIONAL

CAND SURVEYOR

CEPLON K. In Albork

OREGON

JULY 9, 2001

STEPHEN K. HADDOCK

56295LS

RENEWAL DATE 6-30-11