


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by C.E. Redfield in Bureau of Indian Affairs Indian Allotment Survey, dated 1919.

T 1 N R 35 E J-10



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found a 2" iron pipe with 2 1/2" brass cap, marked as shown, at the Northern toe of a rock berm for a pond.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

From the iron pipe position, I take new accessories:


**NEW BEARING TREES:**

A 5" Douglas Fir bears South 27° East, a distance of 16.00 feet, marked W 1/16 S16 BT.  
A 10" double boled White Fir bears North 3.15 feet, marked W 1/16 S9 BT.

I hereby certify that the corner was perpetuated April 12, 2017.



Renewal Date: June 30, 2019



I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.