Emigrant Springs State Park Survey Section 29, T1N, R35E, W.M. August 28, 1981 Page 5

Section Corner 30 29 V-5

Original:

Var. 20150

Set basalt stone 9"x8"x7", 6" in ground for corner 29, 30, 31 and 32. 1 notch on south and 5 notches on east edges.

10" pine N75°E, 72 links, "T1N R35E S29 BT". (Parks Crew found 24" ponderosa pine at fence corner.)

18" pine S76°E, 138 links, "T1N R35E S32 BT". (Parks Crew found 31" ponderosa pine.)

The faces, though well grown over, were obvious and were not chopped out.

Parks Crew Set:

At the intersection of the distances from the bearing trees a 5/8"x30" capped iron rod marked "Oregon State Parks" and erected mound of rock around rod.

9" ponderosa pine S4°30'W, 11.2' to center, scribed "TIN R35E S31 BT".

17" ponderosa pine N36°15'W, 99.8' to center, scribed "T1N R35E S30 BT RS691".

Witnessed by:

- A. Slack
- R. Hemmer
- L. Boge
- S. Morrison

権 Corner Section 29 and 30 ブー5

Original:

Var. 2012°

Set post 3' long, 3" square, 24" in ground, marked "4S" on west face.

36" red fir N45°W, 29 links " $\frac{1}{3}$ S BT". (Parks Crew found 37" rotted red fir stump with "BT" visible, set corner record bearing and distance from this tree.)

. 12" pine S69°E, 80 links "%S"BT". (Parks Crew found rotted pine stump S66°E, 56.8' to center.

Parks Crew Set:

5/8"x30" capped iron rod marked "Oregon State Parks".

16" fir S82°E, 33.3' to center, scribed "Wa S29 BT". Set Parks corner tag.

12" fir N6°W, 24.5' to center, scribed "E4 S30 BT RS691".

Corner is approximately 8 feet west of a north-south fence line.

Witnessed by:

- R. Hemmer
- L. Boge
- L. Hettema

Center & Section 29 T-7

Parks Crew Set:

RECLIVED BY

5/8"x30" capped iron rod marked "Oregon State Parks".

Umatilla County Surveyor
Date 11-81
Rec'd - y BLS

Emigrant Springs State Park Survey Section 29, T1N, R35E, W.M. August 28, 1981 Page 6

7' steel post with white boundary paddle marked "Oregon State Park Boundary Do Not Disturb", 2.0' northeast of iron rod.

17" fir N29%°E, 77.3' to center, scribed "0% S29 BT". Set Parks corner tag.

Power pole N57½°W, 68.8' to center.

Corner of new fence S84°E, 33.2'.

Corner monument is located in a newly cleared area of gas pipeline.

Witnessed by:

- A. Slack
- R. Hemmer
- L. Boge
- S. Morrison

John E. Hollingswort

John E. Hollingsworth Oregon State Parks 525 Trade Street SE Salem, OR 97310

TECLIVED BY

Umatilla County Surveyor

Date 11-81

Rec'd Ly 620

No S-124