Index File No C-2 T1N R. 38E	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7151.4) Survey No No No
Merid. Willamette	R.D. Walla Walla County Union  N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND None
Sec 6 C — C W 1/16	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None
PHOTO IDENTIFICATION DATA	
Photo No.F <u>16616160 1577-12</u> 6	
Object Ident. <u>Direct</u> dent. By <u>G. Langlitz</u>	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7 LANE COORDINATE POSITION DATA	Corner located along N-S cutting line approx. 50' South of a jeep road.
tate Zone	
stob. By	
Signature O.A	Title Division 099 Heodquorters Date 7100-52 (3.68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT TINR38E Corner set from survey by single proportionate measurement along ... W 1/16 C -+ E-W centerline of Section 6.

At the corner point, we set a 2"x30" galvanized iron pipe, 25" in the ground with brass cap attached, marked:

1980

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

From which we mark new BT's:

A 14" Spruce, scribed "CW 1/16 S6 BT" on a double blaze bears N74 $^{12}$ OW 8.2 ft., And a 12" Douglas Fir, scribed "CW 1/16 S6 BT" on a double blaze bears S45 W 25.0 ft. Attached brass washer, marked "LS 1099" to lower blaze of each BT. Placed steel fencepost 5 ft. S of monument with signs 54-2 and 54-9 attached. Attached signs and painted BT's per Standard Specifications For Cadastral Survey, U.S.F.S.

Region 6. October 1979. Work Done By. Gary Langlitz Title Land Surveyor Dote 10-7-80 State Registration No. PLS 1099 Date Dec. 1980 Filed At: Union County Surveyor Certified Cor. Record Prepared ? YAS REMARKS

Compass Declination: 180 East

Witness: John Curtiss

Cor.

10