USDA-FOREST SERVICE	
Index File No G-2	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7151.4) Survey No. No.
T <u>1N</u> R. <u>38E</u>	(Ref. FSM 7151.4) Survey No No No No
Merid <u>Willamette</u>	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec 7	None
W 1/16	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND .  None
PHOTO IDENTIFICATION DATA Photo No Filed At	
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	Corner located approx 2001 West C
PLANE COORDINATE POSITION DATA	Corner located approx. 800' West of a graveled road, U.S.F.S. road No. 3200 161.
State Zone X Y Estab. By	
Jang Konglis La	nd Surveyor PLS 1099 Heodquarters Date 7100-52 (3.68)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Corner set from survey at location determined by subdivision of section.

At the corner point, we set a 2"x30" galvanized iron pipe, 26" in the ground on a steep East slope, with brass cap attached marked:

p attached <u>marked</u>:

W 1/16
PLS 1099
1980

Tract or Surv. No.

TIN

 $C \rightarrow V C$ 

R38E

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE From which we mark new BT's:

A 12" Larch, scribed "CW 1/16 S7 BT" on a double blaze bears N54½0W 67.3 ft., A 12" White Fir, scribed "CW1/16 S7 BT" on a double blaze bears S560W 24.5 ft. Attached brass washer marked "LS 1099" to lower blaze of each BT. Placed steel fenceposts 5' S and E of monument with signs 54-2 and 54-9 attached. Attached signs and painted BT's per Standard Specifications for Cadastral Survey U.S.F.S. Region 6, October 1979.

Work Done By Gary Langlitz Title Land Surveyor Dote 10-10-80 State Registration No. PLS 1099

Certified Cor. Record Prepared ? Yes No Filed At: Union County Surveyor Date Dec. 1980 11

REMARKS

Compass Declination: 180 East

Witness: John Curtiss

Index File No. G-2

Cor.

- - -