## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

V - 19 DIAGRAM

## History of original corner establishment:

The original corner was established by George S. Pershin, deputy, (compassman) on October 27, 1871, under joint GLO contract No. 154, as follows:

T1S R30E 1/4 <u>S26</u> S35 PLS 1636 2002

Set a stone, 18" x 8" x 5", for 1/4 section corner.

## Original corner evidence recovered:

Found the original corner stone loosely set in a mound of stones. Corner stone is  $18" \times 10" \times 4"$  and is plainly marked "1/4" on one face.

## Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 30" flared, galvanized iron pipe 27" into the ground. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above. I bury the corner stone along the south side of the pipe and build a mound of stones around the pipe, from which:

A  $5/8" \times 36"$  iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N62° E, 183.8 feet.

A 5/8" x 24" iron rod set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S46° E, 167.5 feet.

A 5/8" x 24" iron rod set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S47° W, 174.6 feet.

A 5/8" x 36" iron rod set 34" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N43° W, 138.2 feet.

I nailed a "Witness Post" sign to a wooden fence post one foot east of the corner.

I hereby certify the above corner point was perpetuated as hereon described on March 3, 2002. Magnetic declination set in compass: 18° E.

PROFESSIONA AND SUPPLY

Renews June 30, 2003

DENNIS L. GAYLORD

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

0

RECEIVED BY
Umatilla County Surveyo

Rec'd By K P