

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

X - 17
DIAGRAM

History of original corner establishment:

The original corner was established by George S. Pershin, deputy, (compassman) on October 28, 1871, under joint GLO contract No. 154, as follows:

T1S R30E
1/4
S34|S35
PLS 1636
2002

Set a stone, 18" x 6" x 5", on south hillside for 1/4 section corner. Va: 24° 48' E

Original corner evidence recovered:

Found the original corner stone loosely set in a mound of stones. The corner stone is 17" x 9" x 6" and is plainly marked "1/4" on one face.

Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 18" flared, galvanized iron pipe 11" into the ground to bedrock. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above. I bury the corner stone along the east side of the pipe and build a mound of stones around the pipe, from which:

A 5/8" x 24" iron rod set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N53° E, 162.2 feet.

A 5/8" x 18" iron rod set 14" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S30° E, 71.7 feet.

A 5/8" x 18" iron rod set 18" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S72° W, 76.6 feet.

A 5/8" x 18" iron rod set 18" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N42° W, 74.1 feet.

I nail a "Witness Post" sign to a wooden fence post 7.5 feet north of the corner.

I hereby certify the above corner point was perpetuated as hereon described on March 13, 2002. Magnetic declination set in compass: 21° E.



Renews June 30, 2003

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY
Umatilla County Surveyor
Date 6-02
Rec'd By KR
No. 02-146-R