# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## X - 21 DIAGRAM

#### History of original corner establishment:

The original corner was established by George S. Pershin, deputy, (compassman) on October 26, 1871, under joint GLO contract No. 154, as follows:

Set a stone (basalt), 17" x 8" x 6", on south hillside for 1/4 section corner.

	T1S R30E	
ì	1/4	
	S35 S36	
	PLS 1636	
ĺ	2002	

### Original corner evidence recovered:

Found the original corner stone solidly set but tipped to the north. The corner stone is 18" x 8" x 7" and is plainly marked "1/4" on the east face.

#### Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a 1" x 18" flared, galvanized iron pipe 8" into the ground to bedrock. A 2 1/2" brass cap attached to the top of the pipe is marked as shown in the diagram above. I place the corner stone horizontally along the south side of the pipe and build a mound of stones around corner stone and the pipe, from which:

A 5/8" x 24" iron rod set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N22° E, 105.2 feet.

A 5/8" x 24" iron rod set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S60° E, 75.4 feet.

A 5/8" x 24" iron rod set 24" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S73° 45' W, 131.8 feet.

A  $5/8" \times 36"$  iron rod set 35" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N47° W, 165.6 feet.

I hereby certify the above corner point was perpetuated as hereon described on March 3, 2002. Magnetic declination set in compass: 16° E.

PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1978 DENNIS L. GAYLORE

Renews June 30, 2003

Recorded at the office of County Surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY

Umatilla County Surveyd

Date 6-02

Rec'd By KF No. 02 - 141