OREGON CORNER RESTORATION FORM


31E Section 4 Township 18 Range Umatilla October 4, 2001 Date: County Condition Report Only Not found Corner Designation: 1S31A9 Remonumented Unrecorded North section corner to sections 4 and 5, T1S, R31E, W.M., Umatilla County, Oregon. Surveyed in Referenced out

Previous Renewals / Surveys, etc.

The corner was originally set by David P. Thompson under contract No. 106 dated August 16, 1864. His record reads: Set stone 18 x 15 x 8 in. for corner to secs. 4 & 5. The County Surveyor, Aubrey Perry, in the survey recorded in Book 2, Page 301 of the Record of Private Surveys records the original stone had been moved and the marks were not plain. He said "Reset rock on line for Sec. 4-5-S marked II on W - IIII on E.". In County Survey H-7-B, Donald Staebler, Engineer 5408, said "Found stone. Set Brass Cap."

Monument and Accessories found: (condition and source)

The brass cap set by Staebler in a mound of stone with a steel guard post and monument sign along side.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

For references, I set four 5/8" by 24" rebars with 1 1/4" red plastic caps stamped ORLS 852, and WALS 13922 as described below:

an iron rebar bears N0°10'12"E, 23.62 feet, 18" below the surface; an iron rebar bears S84°10'43"E, 23.87 feet, 18" below the surface; an iron rebar bears S1°51'36"W, 24.31 feet, 18" below the surface; an iron rebar bears N89°12'04"W, 25.63 feet, 18" below the surface;

The monument and references were tied using a LIECA SYSTEM 300 RTK GPS.

Location and comments
OR SPC Oregon North 1983-91
N = 677882.79
E = 8597794.42

RECEIVED BY:
Umatilla County Surveyor
Date: 12/20/2001
Rec'd By: 10/1/C

Compass Declination

Firm / Agency Haddock Surveying Address P.O. Box 1574 Pendleton, Or. 97801 Party Chief Stephen K, Haddock Surveyors Seal

PROFESSIONAL LAND SURVEYOR

REGISTERED

OREGON JULY 12 1966 DAVID L. HADDOCK 852

RENEWS 6-30.03