CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

N-13 Index:

Corner, Secs. 15, 16, 21, & 22, T1S, R32E, WM.

Corner originally set by Daniel Chaplin in contract 107 dated Sept, 21, 1864, his record reads: Set post for Cor. to secs 15, 16, 21, and 22, in mound of earth with charred stake, pits, trench, etc. as per instructions.

Ī	DIAGRAM	
ľ	T1S R32E	
i	S16 S15	
Ì		
i	S21 S22	
İ	1 9 95	
	PLS 852	
i		
1		

Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner: The corner is at the intersection of a fence which runs East and West with a fence that runs to the south. This fence corner was called acceptable and used in survey Q-863-B by PLS 346. I set a 1 1/2"x30" Galvanized Iron Pipe with a 2 1/2" Brass Cap for a witness corner 5' West of the true corner point on line stamped as in the diagram above. The witness monument and the bearing objects are recorded in relation to the true corner location.

> REGISTERED PROFESSIONAL LAND SURVEYOR

DAVID L. HADDOCK

David L. Haddock A 5/8"x24" rebar with 2" Al cap bears S01°20'W, 30.0', stamped B.O., ORLS 852, AND WALS 13922. OREGON JULY 12, 1968

A 5/8"X24" rebar with 2" Al cap bears N0°00'E, 1.5', stamped

B.O., ORLS 852, AND WALS 13922.

A 5/8"X24" rebar with 2" Al cap bears N88.51'W, 30.0', stamped B.O., ORLS 852, AND WALS 13922. A 5/8"X24" rebar with 2" Al cap bears S89°32'E, 30.0', stamped

B.O., ORLS 852, AND WALS 13922.

The bearings are based on the section line to the south being S00°28' 33" W.

This work was done Septmember 27, 1995 and witnessed by Stephen Haddock.

Office of Survey Dept. County of Umatilla

State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 2324 day of october, 1995. by . (COUNTY OFFICIAL) (DEPUTY)

Umatilla County Surroyor