CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index:

R-13

Corner, Secs. 21, 22, 27, & 28, T1S, R32E, WM.

Corner originally set by Daniel Chaplin in contract 107 dated Sept, 21, 1864, his record reads: Set post for Cor. to secs 15, 16, 21, and 22, in mound of earth with charred stake, pits, trench, etc. as per instructions.

DIAGRAM T1S R32E S21 | S22 S28 | S27 1995 PLS 852

Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner:

The corner is at the corner of a fence with fences running North and West. This fence corner was called acceptable and used as the corner in surveys Q-863-B and 92-88-B by PLS 346. I set a 1 1/2"x30" galvanized iron pipe with a 2 1/2" Brass cap stamped as in the diagram above 5' west of the true corner location on line for a witness monument. The witness monument and the bearing objects are all recorded in reference to the true corner location.

A 5/8"x24" rebar with 2" Al cap bears NO2°25'E, 29.9', stamped

B.O., ORLS 852, AND WALS 13922. A 5/8"X24" rebar with 2" Al cap bears N45°13'W, 14.9', stamped

B.O., ORLS 852, AND WALS 13922.

A 5/8"X24" rebar with 2" Al cap bears S33°52'E, 1.5', stamped

B.O., ORLS 852, AND WALS 13922. A 5/8"X24" rebar with 2" Al cap bears S89°15'W, 30.0', stamped

B.O., ORLS 852, AND WALS 13922. The bearings are based on the section line to the north being N 00°28' 33" E.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DAVID L. HADDOCK

David L. Haddon

This work was done Septmember 27, 1995 and witnessed by Stephen Haddock.

Office of Umatilla Survey Dz	at. County of Umatilla
State of ORSAON, I hereby cer	tify that the within instrument was filed 23 day of October, 1995.
(COUNTY OFFICIAL)	(DEPUTY)

RECEIVED BY

Umatilla County Surveyor

Date / Bee'd Dy K

No. 95-187-R