OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 10/5/94

CORNER DESIGNATION: Z-15. South 1/4 corner Section 34, TlN., R35E., W.M.

PREVIOUS RENEWALS/SURVEYS, ETC.: Most recent approved GLO Survey was made by James P. Currin and James Noland, under Special Contract dated May 4, 1887. Notes state: "Set basalt stone 16 x 12 x 9 ins., 10 ins. in the ground at exact place of old cor. for 1/4 sec. cor., marked S.C. 1/4 on N. face, from which: A Pine, 12 ins. in diam. (old B.T.) bears S.20°E 45 lks. dist., marked S.C.1/4 S.B.T. A Pine, 10 ins. in diam. bears N.26°E. 54 lks. dist., marked S.C.1/4 S.B.T. The other old bearing tree has been cut down."

Reference to old corner and accessories are from original survey record by Timothy Davenport, Contract No. 102, dated July 20, 1863.

MONUMENT AND ACCESSORIES FOUND: None. Corner re-established by single proportionate measurement between the recovered Southwest corner of Section 34 and the recovered Southeast corner of Section 34.

MONUMENT MARKING DETAIL:

TIN R35E S34 S3 TIS R35E 1994 PLS 1106

MONUMENT SET:

At position determined by survey set a 2 1/2" brass cap on 1 1/4" x 12" flared galvanized iron pipe, 16" in the ground to solid basalt, (cap marked as shown in monument detail). Corner falls in pavement.

New Accessories:

A 6" lodge pole pine bears N 78° W-125.1 feet, scribed: 1/4 34 SC

A 7" lodge pole pine bears N 05° E-149.0 feet, scribed: 1/4 S34 SC BT.

A brass washer by electrical junction box, at northwest corner of gravel shed bears S 64° E-119.5 feet.

A brass washer at the base of power pole #035900, Umatilla Rural Electric Association, bears S 12° W-136.3 feet.
Bearing trees have a brass washer stamped 'PLS 1106' nailed to the

face of the blaze. Attached bearing object and witness signs to each tree, painted a 6" band and face of blaze red. Attached bearing object and witness signs near brass washers.

LOCATION & COMMENTS: Corner falls in centerline of intersection of Highway 30 and Horseshoe Ridge Road at the state gravel sheds.

STATE PLANE CO-ORDINATE:

Oregon North Zone, NAD 83/91, U.S. Survey Foot:

N = 680726.20E = 8733890.69

COMPASS DECLINATION: 18° East.

Surveyor's Seal

REGISTERED

PROFESSIONAL

LAND SURVEYOR

Willi R. Wells OREGON

JULY 22, 19/7 WILLIAM R. WELLS

FIRM/AGENCY: William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

Party Chief: Robert D. English

Notes: Robert D. English Witness: F. Scot Munro

RECEIVED BY

Date 2-95

1106 Renews 6/30/96

Umatilla County Surveyor

Bed'd By_ 95-110-(