USDA-FOREST SERVICE Index File No. 0-23 T 15 R. 35 E Merid. WILLAMETTE	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. No. R.D. WALLA WALLA County UMATILLA N.F. UMATILLA State OREGOA
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
N (N 1/16 524)	3'14" BLM BRASS CAP IN MOUND OF SPONES
1984	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND (O" P. PINE BLAZEP & SCRIBED CN/16 524 BT BEARS W 68/2°E ~ Z9'Z LKS
PHOTO IDENTIFICATION DATA Photo No Filed At.	11" P. PINE BLAZED & SCRIBED CN 1/16 524 BT BEARS 5 60° E 87 1/2 LKS
Object Ident.	3
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7	IN BOTTOM OF SMALL RAVINE, EAST OF CLEARING.
PLANE COORDINATE POSITION DATA Stote Zone X Y	ON POSTED W-5 & SEC 24'
Estab. By	
Agency 8	4
Ballow	Title Division Headquarters Date 7100-52-(3, 68) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT NONE

ACCESSORIES : DESCRIBE NEW 81'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

SET STEEL FENCE POST

ATTACHED SIGNS TO POST & BT'S. PAINTED RED BANDS.

· · · · · · · · · · · · · · · · · · ·		10
WORK Done By B.A. SUTTON TITLE SURVEYOR	Date 7-85 State Registration No. LS 1848	
Certified Cor. Record Prepared ? Yes No X Filed At:	Date	11
REMARKS		

Index File No. T.IS R.35E WM. Tract or Surv. No. Cor. 0-23