## REPORT ON CONDITION OF FOUND GOVERNMENT CORNER


Robert Butler

#### December 11, 1996

Umatilla Conuty

### Description of Corner as Set:

This corner was set in 1984 by Lawrence D. Holmes, BLM cadastral surveyor, as part of a dependent resurvey under special instructions dated September 22, 1983, group number 1184, Oregon.



The field notes state:

Set an iron post, 30" long, 2½" diameter, with magnetic, plastic breakaway base, 26" in the ground with brass cap marked:

T1S R35E C ¼ S 24 1984

#### From which:

A Douglas fir, 8" diameter, bears N 49 3/4° E, 54 LKS dist., mkd. C ¼ S24 Bt. A Ponderosa pine, 15" diameter, bears N 50½° W, 56 LKS, dist., marked C ¼ S24 Bt.

# Description of Corner Evidence Found:

Found 3" brass cap protruding 6" out of ground, in good, solid condition,

### From which an:

18" Ponderosa pine bears N  $50\frac{1}{2}$ ° W, 56 LKS, with partially healed blaze.

10" Douglas fir bears N 49 3/4° E, 54 LKS., with partially healed blaze.



Caratilla County Surveyor
Date 13-96
Reo'd By 194-R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Hobert & Buttos
OREGON
JULY 25, 1995
ROBERT E. BUTLER
2733

Expires 12/31/97
Oregon Dept. of Transportation
3012 Island Avenue
La Grande, OR 97850