USDA-FOREST SERVICE	
Index File No. <u>A-19</u>	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No
T1S R36E	Ref. FSM 7151.4) Survey No.
MeridWILLAMETTE	N.F. UMATILLA State OREGON
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
S 2	Corner not previously established. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND Corner not previously established.
PHOTO IDENTIFICATION DATA 12 616140A 787-111 Photo No. Filed At. Ranger Office Object Ident. Bearing Trees Ident. By D.I. Griffith Signature 7 PLANE COORDINATE POSITION DATA State Zone	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner falls on steep Northwest slope with scattered timber approximately 2200 feet East of the railroad track and approximately 200 feet North of the top of the ridge.
Estab. By Aggy () 6	Title Division Headquarters Date 5-7100-52 (3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
Set a 2½"x30" aluminum pipe with aluminum cap marked as shown:

T1N R36E

m cap marked as snown:

½ S 2 T1S R36E 1989 OPLS 644

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

New BTs:

A 16 inch diameter Ponderosa Pine bears S65°W, 73.54 feet marked ½ S2 BT A 14 inch diameter Ponderosa Pine bears N38°W, 7.65 feet marked X BT (No other tree available to the South)

Painted a 6 inch red band around all bearing trees and attached 54-3 and 54-9 signs.

Set a steel fence post approximately 5 feet East with 54-9 sign attached.

Work Done By D. I. Griffith
Title Surveyor

Onte Date or Agency

Certified Cor. Record Prepared 7 Yes No Filed At: Umatilla Co. Surveyor's Office Date 9-89

REMARKS

Witnesses: Rick Robinson and Jeff Petersen

Pipe is set 26 inches in the ground.

Tract or Surv. No.

Cor.