
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established in 1882 by Herman D. Gradon under General Land Office Contract Mo. 452.

Surveyor General Records (notes) states: Set a basalt stone  $12 \times 9 \times 5$  ins. 8 ins. in the ground

for 1/4 Sec. Cor. makred 1/4 on W face, from which A pine 20 ins. diam. bears N50°W 112 lks. dist. marked 1/4 S BT.

No other tree within limits and raised a mound of stone alongside.



(No subsequent remonumentations in county records)

## Description of corner evidence found:

Found 26 in. pine live in good condition with scribing visible, established corner position \$50°E 74 ft. distance from BT.

## Description of monument and accessories I established to perpetuate the original location of this corner

Set 30 in. x  $2\frac{1}{2}$  in. Iron pipe with 3 in. brass cap marked as shown 26 in. in the ground and raised a mound of stone around the pipe for the 1/4 corner between Sec. 1 and 2, from which a new ST -

A fir 16 in. diam. bears \$12°E 11.4 ft. dist. marked TIS R36E 1/4 \$1 BT.

Distance taken to a brass washer in the blaze of the ST.
Set a steel fence post approximately 5 ft. North from corner with Forest Boundary sign attached.

T I S R 36E

S 2 S I

1/4
1972
PLS 848

Used steel tape and magnetic compass with declaration =  $20^{\circ}$  East.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON DOUGLAS M. FERGUSON 848

Office of State of Land Land County of County