
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Umatilla County survey records.

Description of corner evidence found:

Corner not previously established.

See map of survey dated September, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground, from which:

New Bearing Trees: A 8 inch diameter Douglas Fir bears S32°E, 35.61 feet marked X BT A 10 inch diameter White Fir bears S40°W, 10.82 feet marked S 1/16 S2 BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet North with land survey monument and property boundary signs attached.

I hereby certify that the above corner point was perpetuated as hereon described on August 18, 1989.

Witness: Jeff Petersen

T1S R36E S 1/16 S 2 | S 1 1989 OPLS 644

LAND SURVEYOR

REGISTERED PROFESSIONA

DUANE I. GRIFFITH

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of the Survey Dept. County of Umatikla

State of Description of the within instrument was filed in this office for record on the R. day of Details by Matheway & Amshey (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

RECEIVED BY

*GPO-591-971, 1988

...

Des 10-89 Basic KA No. 89-101-B

D-21