
History of original corner establishment: Corner established in 1881 by Jacob C. Cooper under General Land Office Contract No. 397.

Surveyor General Records (notes) states:

A mound of earth 5 ft. at base, 2 ft. high with pits, Set post 42 ft. long 4 in. square, 2 ft. in mound Rase \$7 on table land marked TIS \$6 on ME, R36E \$7 on \$E, R351, \$11 on \$W and \$1 on the MW face, 5 notches on the \$1 and \$1 notch on the north edges,



From which

A pine 30 in. diam. bears $N3^{\rm OE}$, 76 lks. dist. marked T1S, R36E, S6 BT. A pine 22 in. diam. bears $M62^{\rm OW}$, 72 lks. dist. marked T1S, R35E S1 BT. A pine 20 in. diam. bears $S76^{\rm OW}$, 92 lks. dist. marked T1S, R35E S12 BT. Also a pit in Sec. 7

A double set of corners was established on this line in a subsequent survey.

Description of corner evidence found: (No subsequent remonumentations in county records)

Found 36 in. penderosa pine, living, in good condition, with scribing clearly visible, bearing N3°E 50.0 ft. dist. from the cerner position.

Found 22 in. pine down and rotten with scribing clearly visible, bearing $N62^{\circ}W$, 47.5 ft. dist. from the corner position.

Description of monument and accessories I established to perpetuate the original location of this corner


Set a 30 in. $\times \frac{51}{2}$ in. Iron pipe with brass cap marked as shown, 26 in. in the ground and raised a mound of stone around the pipe for the corner between Sec. 6 & 7.

From which new 8T's

A fir 18 in. diam. bears $$40^{\circ}E$, 14.2 ft. dist. marked TIS, R36E, S7 9T.

A fir 14 in. diam. bears $845^{\circ}W$, 25.5 ft. dist. marked T1S, R35E, S1 ST.

Distances taken to a brass washer in the blaze of each tree. Set a steel fence post approximately 5 ft. North from corner with Forest Boundary sign attached.



REGISTERED PROFESSIONAL LAND SURVEYOR

Used steel tape and magnetic compass with declination = 20°E.

OREGON DOUGLAS M. FERGUSON 848

Office of County of County

(COUNTY OFFICIAL) (DEPUT